00684.003258 **PATENT** 

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Mile Falent of.	)
	:
NAOJI OTSUKA ET AL.	)

Appln. No.: 09/966,251

Filed: October 1, 2001

PRINTING APPARATUS, PRINTING For: METHOD, DATA PROCESSING METHOD AND RECORDING

MATERIAL

U.S. Patent No.: 7,079,283 B2

Issued: July 18, 2006

December 6, 2006

Examiner: Twler M. Lamb

Art Unit: 2622

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

#### **CERTIFICATE OF CORRECTION** UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

> 18/09/2006 SZEUDIE1 00000051 7079893 C1 70:1832

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Elizabeth F. Holowacz Attorney for Patentees

Registration No. 42,667

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

Facsimile: (212) 218-2200

605451v1 ·

# PRINTER'S TRIM LINE

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,079,283 B2

DATED

July 18, 2006

INVENTOR(S) :

NAOJI OTSUKA ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### ON COVER PAGE AT (\*) NOTICE

"This patent is subject to a terminal disclaimer." should be deleted.

#### ON COVER PAGE AT (30) FOREIGN APPLICATION PRIORITY DATA

"2000/300185" should read --2000-300185--.

#### COLUMN 2

Line 17, "use independent two" should read --using two independent--;

Line 35, "print" should read --printed--;

Line 36, "provide" should read --provides--; and

Line 63, "above" should read --above---.

#### COLUMN 4

Line 38, "above described" should read --above-described--;

Line 53, "to" should read --for--;

Line 54, "patter" should read --pattern--; and

Line 58, "one of" should read -- one or --.

#### COLUMN 6

Line 20, "above described" should read --above-described--;

Line 41, "nozzle," should read --nozzles,--;

Line 44, "has" should read --has been--; and

Line 65, "ink" should read --inks--.

#### MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 7,079,283 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

605451v1

<u>\_\_</u>

MEC 1 3 2006

No. of add'l. copies

@ 30¢ per page

#### **CERTIFICATE OF CORRECTION**

PATENT NO.

7,079,283 B2

DATED

July 18, 2006

INVENTOR(S) :

NAOJI OTSUKA ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 7

Line 27, "covert" should read --convert--; and Line 44, "to" should read --with--.

#### **COLUMN 8**

Line 55, "these" should read --this--; and Line 59, "wording" should read --working--.

#### COLUMN 9

Line 7, "sensors 234" should read --sensor 234--;

Line 17, "(election" should read --(ejection--;

Line 37, "first recording heading" should read --ejecting--; and

Line 42, "(M2)" should read --(C2)--.

#### COLUMN 10

Line 60, "cyan." should read --cyan head.--; and Line 66, "are" should be deleted.

#### MAILING ADDRESS OF SENDER:

PATENT NO. US 7,079,283 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

605451v1

#### CERTIFICATE OF CORRECTION

PATENT NO.

7,079,283 B2

DATED

July 18, 2006

INVENTOR(S) :

NAOJI OTSUKA ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 11

Line 4, "the M1" should read --M1--;

Line 15, "present" should read -- the present--;

Line 18, "and" should be deleted;

Line 45, "he" should be deleted;

Line 47, "write" should read --writes--;

Line 58, "used" should read --use--; and

Line 61, "becomes" should read --become--.

#### COLUMN 12

Line 52, "be" should be deleted.

#### COLUMN 13

Line 15, "In the Figure, (b)," should read -- The Figure (b)--.

#### COLUMN 14

Line 15, "nozzle" should read --nozzles--; and

Line 62, "satisfactory" should read --satisfactorily--.

#### COLUMN 15

Line 14, "apparatuses" should read --apparatus--; and

Line 54, "above described" should read --above-described--.

#### MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 7,079,283 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

605451v1

No. of add'l. copies @ 30¢ per page

#### **CERTIFICATE OF CORRECTION**

PATENT NO.

7,079,283 B2

DATED

July 18, 2006

INVENTOR(S) :

NAOJI OTSUKA ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 16

Line 21, "above described" should read --above-described--;

Line 59, "that pair" should read --that a pair--; and

Line 65, "The printing the defective" should read -- Printing is effected--.

#### COLUMN 17

Line 28, "applied" should read --applies--;

Line 57, "above described" should read --above-described--; and

Line 61, "above described" should read --above-described--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 7,079,283 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

605451v1

DEC 1 3 2006

# Staple Here Only!

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

7,079,283 B2

DATED

July 18, 2006

INVENTOR(S) :

NAOJI OTSUKA ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### ON COVER PAGE AT (\*) NOTICE

"This patent is subject to a terminal disclaimer." should be deleted.

#### ON COVER PAGE AT (30) FOREIGN APPLICATION PRIORITY DATA

"2000/300185" should read --2000-300185--.

#### **COLUMN 2**

Line 17, "use independent two" should read --using two independent--;

Line 35, "print" should read --printed--;

Line 36, "provide" should read --provides--; and

Line 63, "above" should read --above---.

#### **COLUMN 4**

Line 38, "above described" should read --above-described--;

Line 53, "to" should read --for--;

Line 54, "patter" should read --pattern--; and

Line 58, "one of" should read -- one or --.

#### COLUMN 6

Line 20, "above described" should read --above-described--;

Line 41, "nozzle," should read --nozzles,--;

Line 44, "has" should read -- has been --; and

Line 65, "ink" should read --inks--.

#### MAILING ADDRESS OF SENDER:

PATENT NO. US 7,079,283 B2

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

605451v1

No. of add'l. copies

@ 30¢ per page

#### CERTIFICATE OF CORRECTION

PATENT NO.

7,079,283 B2

**DATED** 

July 18, 2006

**INVENTOR(S)** 

NAOJI OTSUKA ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 7

Line 27, "covert" should read --convert--; and Line 44, "to" should read --with--.

#### **COLUMN 8**

Line 55, "these" should read --this--; and Line 59, "wording" should read --working--.

#### COLUMN 9

Line 7, "sensors 234" should read --sensor 234--;

Line 17, "(election" should read --(ejection--;

Line 37, "first recording heading" should read --ejecting--; and

Line 42, "(M2)" should read --(C2)--.

#### **COLUMN 10**

Line 60, "cyan." should read --cyan head.--; and Line 66, "are" should be deleted.

#### MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 7,079,283 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

605451v1

#### CERTIFICATE OF CORRECTION

PATENT NO.

7,079,283 B2

DATED

July 18, 2006

INVENTOR(S) :

NAOJI OTSUKA ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### **COLUMN 11**

Line 4, "the M1" should read --M1--;

Line 15, "present" should read -- the present--;

Line 18, "and" should be deleted;

Line 45, "he" should be deleted;

Line 47, "write" should read --writes--;

Line 58, "used" should read --use--; and

Line 61, "becomes" should read --become--.

#### COLUMN 12

Line 52, "be" should be deleted.

#### COLUMN 13

Line 15, "In the Figure, (b)," should read -- The Figure (b)--.

#### COLUMN 14

Line 15, "nozzle" should read --nozzles--; and

Line 62, "satisfactory" should read --satisfactorily--.

#### **COLUMN 15**

Line 14, "apparatuses" should read --apparatus--; and

Line 54, "above described" should read --above-described--.

#### MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 7,079,283 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

605451v1

@ 30¢ per page

No. of add'l. copies

DEC 1 3 2006

#### **CERTIFICATE OF CORRECTION**

PATENT NO.

7,079,283 B2

DATED

July 18, 2006

INVENTOR(S)

NAOJI OTSUKA ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### **COLUMN 16**

Line 21, "above described" should read --above-described--;

Line 59, "that pair" should read --that a pair--; and

Line 65, "The printing the defective" should read -- Printing is effected--.

#### COLUMN 17

Line 28, "applied" should read --applies--;

Line 57, "above described" should read --above-described--; and

Line 61, "above described" should read --above-described--.

#### MAILING ADDRESS OF SENDER:

PATENT NO. US 7,079,283 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

605451v1

No. of add'l. copies . @ 30¢ per page

